

Lessons Learned

- Machining always takes longer than you predict!
- Leave time for redesigns
- Shop managers are lifesavers
- Designs needs to be validated again after ANY design changes.
- Evaluate every assumption and is repercussions thoroughly
- Thermosyphoning is still magic...