

Team P17046

Engineer: Jason Constant

Entering Phrase: Subsystem Build & Test

What do I plan on doing to ensure that Team P17046 has a successful Phase 7 review?

1. Make sure welded frame is drilled and welded by the next Thursday (3/2).
2. Mount Servos, press in bearings, bore out gear ID to fit onto shafts, press gears onto shafts, and make sure motor shaft fits into gear shaft.
3. Figure out what we are going to use for our prototype's feet and manufacture/ attach them.
4. Mount springs and rack stop onto frame.
5. Calibrate constants in code to make sure the gear system works well in tandem with the servos.

You will answer these three questions when you submit at the end of Phase: Subsystem Build & Test.

1. Was my team on track?
2. Did we have a working prototype Integrated System to demonstrate?
3. Technical Report 50% completed?