

MSD Team P17453

Meeting Notes

3/21/17

Meeting Accomplishments:

- Placed order for correct back pressure regulating valve
- Determined that poppet leak tests were not necessarily conclusive due to the back pressure regulator valve not working as expected.
  - If leakage appears to be a problem, further tests will be conducted
- Uploaded more test videos to YouTube
- Worked on the technical paper
- Added wire connectors to the setup
- Set up SignalExpress to read the second pressure transducer