

**Team:** P17665 – Rotating Dynamometer      **Engineer:** Muhammad Ibraheem  
**Entering Phase: V Build and Test Prep**

**What do I plan on doing to ensure that Team P17665 has a successful Phase III review?**

1. Start watching videos to gain knowledge on strain gauge mounting. (W1)
2. Solder amplifier ICs and bluetooth to prototype boards. (W1)
3. Test Strain Gauges if they arrive. (W1)
4. Mount components into housing with Brian. (W1)
5. Start mounting strain gauges and terminal pads to device (W2)
6. Straighten out details of calibration procedures with the rest of the team (W2)
7. Update EDGE with documentation. (W2)
8. Prepare for next review (W3)

**You will answer these three questions when you submit at the end of Phase (3).**

1. What did I actually do?
2. What did I learn?
3. What do I plan on doing to ensure that Team P16xxx has a successful Phase (N+1) review?