

MSD - Dr Liu Meeting 2

- Mesh not fine enough near deformation point
 - Try tapered shank
 - Ratio of chip load vs max tip deflection
↳ want tip deflection less than an order of mag.
- Force → calculate Chip Load (how?)

Requirements

- doesn't have to be accurate
- has to measure something

Solution

- ★ minimize cross-section in arms