


Push Button Shifting



Gear	Frist	Second	Thrid	Forth	Fifth
Min. RPM value for Up shifting	3000	3000	3000	3000	NA
Max. RPM value for down shifting	NA	7000	7300	7600	7600