

## P14418 - Integrated Systems Demo

Gerry's Comments

- Noise implies wear
- Sealing electronics
- Problem management process lacking
- Mitigation of issues lacking
- Change control process, not all stakeholders are necessarily on board when changes are made in machine.
- Electronics need to be presented in a better way (User needs to be pedaling at a steady rate at the right spot based on device feedback)
- Models may have flaws
  - Electrical
  - Seat

P14417

- Brush test not completed, Bucket durability <sup>test</sup> not started
- Genesee River water was frozen over
- Manufacturing turbidity levels
- ~~Shore~~

Continued to page

SIGNATURE

DATE

DISCLOSED TO AND UNDERSTOOD BY

DATE

PROPRIETARY INFORMATION