


Key:
 SGX1= Strain gauge on front of blade
 SGX2= Strain gauge on rear of blade
 X= Gauge measuring circuit blade 1, 2, 3, or 4



| | | |
|------------------------------------|-----------------------------|--------------|
| Title | | |
| P16315 Strain Gauge Wiring Diagram | | |
| Size | Document Number | Rev |
| A | 1 | 2 |
| Date: | Thursday, December 10, 2015 | Sheet 1 of 1 |
| | 2 | 1 |