

Team: P16315 Engineer: THOMAS KLABEN

Entering Phase: 7

What do I plan on doing to ensure that Team P16315 has a successful Phase (7) review?

1. Finish wiring all gauges and complete gauge waterproof testing
2. Set up the data logger for the customer to be able to data log
3. Start Work on the Paper layout.
4. Start layout of assembly manual.
5. Conduct CSV File size testing.
6. Battery Life testing

You will answer these three questions when you submit at the end of Phase (6).

1. Solder all wires and plugs and one measurement blade.
2. Start Waterproof and range testing and speed testing.
3. Purchased better sealant.
4. I learned that all wire connections must be testing because we had a small portion of wire not insulated, also that our testing is indeed serving a purpose.