

Team: P17310

Engineer: Ahmed Alhurubi, Electrical Engineer

Entering Phase: Phase 2

What do I plan on doing to ensure that Team P17310 has a successful MSD 2 Phase 2 review?

1. Build the connection circuit for slit motor and latch motor with Wilson (1 week)
2. Connect the pressure sensors to latch torque arm with Wilson (1 week)
3. Power the latch motor from the power rails. (1 week)