

MSD Team P17453

Meeting Notes

2/14/17

Meeting Accomplishments:

- Tried figuring out the hardware software setup required in the lab
  - Discovered that we were given incorrect information about how to hook up the 120 V ac power supply, were blowing breakers
- Successfully demonstrated the relays working with an external signal generator after failing to get the software and DAQ to work
- Decided we most likely needed to use digital signals in the DAQ instead of analog signals
- Decided to create a YouTube channel to display videos of testing/progress